


This modification is intended to get the SD-Card working with the SD-AVR, 20200513-WF



SD-Card Modification:
Deinstall R284.
Change value of R276 to 33R0.

Close SJ9.