


This modification connects the SD_IN and SD_OUT of the audio codec correctly, 20200727-WF



Modification:
Interchange pin5 and pin8 of the audio codec.Lift th pins and connect it via enameled copper wire.